




NEW MEXICO HISTORIC BUILDING INVENTORY - SANTA FE RESURVEY 1996

IDENTIFICATION	ADDRESS: <u>515 Paseo de Peralta</u> <u>(previously 133 Hillside)</u>	OLD ID NUMBER: <u>051610566</u>	
	UTM REFERENCE EASTING NORTHING ZONE <u>12 13</u>	LEGAL DESCRIPTION: TNSP <u>17</u> (N) S RANGE <u>9</u> (E) W SEC <u>24</u> NE 1/4 SW 1/4	BUILDING NAME:
	FIELD MAP <u>Santa Fe</u> Historic Status Map 1996	SANTA FE ID NUMBER: <u>H 30040</u>	
BUILDING DATA	DATE OF CONSTRUCTION: by _____ ESTIMATE <u>1890</u> ACTUAL _____ SOURCE(S) <u>owners</u>	 <p>#26 south elevation</p>	
	ARCHITECTURAL STYLE: <u>Neoclassical</u>		
	USE: HISTORIC: <u>residential</u> OTHER _____ PRESENT: <u>residential</u> OTHER _____		
	SURROUNDINGS: <u>residential/commercial</u>		
BUILDING DATA	RELATIONSHIP TO HISTORIC SURROUNDINGS: <input checked="" type="checkbox"/> SIMILAR <input type="checkbox"/> NOT SIMILAR	 <p>1/4" = 10'</p> <p>251 Paseo de Peralta 26 27</p>	
	ASSOCIATED BUILDINGS ON SITE: <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO WHAT TYPE? <u>shed, garage</u> IF INVENTORIED, LIST ID NUMBER(S) <u>H 30041, H 30042</u>		
	DEGREE OF REMODELING: <input type="checkbox"/> MINOR <input checked="" type="checkbox"/> MODERATE <input type="checkbox"/> MAJOR <u>porch remodel, addition 1940s</u> EXPLAIN: <u>addition 1940s</u>		
SIGNIFICANCE	OVERALL CONDITION: <input type="checkbox"/> EXCELLENT <input type="checkbox"/> GOOD <input checked="" type="checkbox"/> FAIR <input type="checkbox"/> DETERIORATED	LISTED ON NATIONAL REGISTER OF HISTORIC PLACES? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/> ELIGIBLE <input checked="" type="checkbox"/> CONTRIBUTING <input type="checkbox"/> NON-CONTRIBUTING	
	BUILDING THREATENED? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	LISTED ON STATE REGISTER OF CULTURAL PROPERTIES? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/> ELIGIBLE LOCAL DESIGNATION: <u>Downtown-Eastside</u> HISTORIC DISTRICT <input checked="" type="checkbox"/> SIGNIFICANT <input type="checkbox"/> CONTRIBUTING <input type="checkbox"/> NON-CONTRIBUTING LOCAL LANDMARK <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	

SURVEYED 5/96 BY DB

NEGATIVES WITH NMHPD ROLL # DB1 NEG # 25 TO 31 & 36

ARCHITECTURAL FEATURES: STYLE, MATERIALS, AND CONDITION	ROOFS & DRAINS	Shed with brick coping, stabilized with concrete & asphalt along top row; flat w/ asphalt roofing	
	BUILDING WALLS	tan textured stucco over double brick	
	FOUNDATIONS	stone (visible under porch)	APPROX. HEIGHT (FT.) 20
	DOORS	S - wood with double arched light N - wood panel w/ 4 lights, wood panel w/ 2 lights, wood panel w/ single light - all w/ old wood screens	
	WINDOWS	paired and single 2/2 wood DHWs in double or single segmental openings, old glass (windows at S center in flat openings); 6/6 wood DHWs on NE	
	PORCHES OR PORTALES	center S - projecting "tower" with arched openings, stuccoed brick banister, approached by curving steps on E; concrete stoop SE w/ steps; brick steps NE corner	
	ARCHITECTURAL DETAILS	string course on parapet, windows in segmental recesses, brick evident under stucco - stucco has deteriorated & is patched on porch.	
	FENCES/WALLS	stone wall all along property, S on street (no side-walks) with stone steps	
	SITE FEATURES	stone retaining walls at street and at intervals up the slope; large concrete retaining wall on N	
	OTHER/ COMMENTS	In 1940s, porch was partially demolished and west stairs removed. Addition on NW 1940s with clearly different windows (3 light awning). Shed at NW very old, exposed adobe w/ metal roof.	



NEW MEXICO HISTORIC BUILDING INVENTORY - SANTA FE RESURVEY 1996 (concluded)

IDENTIFICATION

ADDRESS

515 Paseo de Peralta

ID NUMBER: 051610566

SANTA FE ID NUMBER: H30040

SURVEYED/RESEARCHED

DATE 5/96 BY DB



#30 north elevation, W end



#29 north elevation, E end



#28 east elevation



Faint, illegible text at the top of the page, possibly a header or title.

Main body of the page containing several paragraphs of extremely faint and illegible text.

Faint, illegible text at the bottom of the page, possibly a footer or page number.

NEW MEXICO HISTORIC BUILDING INVENTORY - SANTA FE RESURVEY 1996 (concluded)

IDENTIFICATION	ADDRESS	ID NUMBER: 0516 10566
	515 Paseo de Peralta	SANTA FE ID NUMBER: H30040
		SURVEYED/RESEARCHED
		DATE 5/96 BY DB



#27 southeast



#31 shed from SW

THE UNIVERSITY OF CHICAGO

PHYSICS DEPARTMENT

PHYSICS 310

LECTURE 1

LECTURE 2

LECTURE 3

LECTURE 4

LECTURE 5

LECTURE 6

LECTURE 7

LECTURE 8

LECTURE 9

LECTURE 10

LECTURE 11

LECTURE 12

LECTURE 13

LECTURE 14

LECTURE 15

LECTURE 16

LECTURE 17

LECTURE 18

LECTURE 19

LECTURE 20


LECTURE 21

LECTURE 22

LECTURE 23

LECTURE 24

LECTURE 25



515 Paseo de Peratta
(133 Hillside) 1948 Sanborn

UNPAVED



JAN. 1930
SANTA FE
N. MEX.



39

40

38
(111)

41

REINGARDT ALLEY

E. MARCY

37 A
(3 1/2)

NUSBAUM

OTERO

9


42
(137)


CIENEGA

43
(137)

37 B
(3 1/2)


COURT RM 2'






House on Paseo de Reina (Formerly Hillside Avenue)
ca 1910-15 (glass 8x10)

MNM # 516 31






Hansen Hillside Avenue

ca 1907-12

(Water-colored print)

MNM # 10516

(Dorman Coll.)



June 19, 1995
Box 1218
Mesilla, NM 88046

Historic Design Review Board
City of Santa Fe
200 Lincoln Ave
P.O. Box 909
Santa Fe, N.M. 87504-0909

Re: 515 Paseo de Peralta, Area #1, House #533, "Significant".

Dear Historic Board Members:

This proposal is for the repair and restoration of the exterior stucco, exterior wood surfaces, and structural integrity of the front porch on significant historic building #533, located at 515 Paseo de Peralta (Ex. A).

The building is of double brick construction covered with a rough cement stucco. The existing stucco was probably applied at the time of original construction. The bricks are roughened and pocked to hold the stucco without lath. The brick faces do not show signs of ever having been the exterior surface. I know that the existing stucco has been in place since 1937 when the building was purchased by my parents. At that time the stucco appeared to be old (See 1937 photo at Ex. B).

Due to weathering and age, the stucco has peeled and cracked in several places. There are large cracks with missing bricks in the front porch. It is proposed that those bricks be replaced and the cracks filled with a non shrinking filler. Lath would be used as necessary to hold the new stucco. The porch structure will be reinforced for safety with steel bands and plates which will be covered with stucco. This plan was recommended and endorsed by Ken DeLapp, professional and structural engineer (Ex. C).

The brick pattern in the parapets will not be covered by new stucco. The wood in the eaves, window frames, and doors will be scraped and painted. Rotten wood will be replaced as needed. The original configurations will be maintained.

The earliest record of a building on this site which I have been able to find is dated December 13, 1872 in Book Q Deeds at Page 256 and refers to "tenements and apputenances thereunto". This was on a deed filed October 1, 1887 transferring title. It is unknown to me if the "tenements and apputenances" were the existing building.

1941
1942
1943
1944
1945
1946
1947
1948
1949
1950
1951
1952
1953
1954
1955
1956
1957
1958
1959
1960
1961
1962
1963
1964
1965
1966
1967
1968
1969
1970
1971
1972
1973
1974
1975
1976
1977
1978
1979
1980
1981
1982
1983
1984
1985
1986
1987
1988
1989
1990
1991
1992
1993
1994
1995
1996
1997
1998
1999
2000
2001
2002
2003
2004
2005
2006
2007
2008
2009
2010
2011
2012
2013
2014
2015
2016
2017
2018
2019
2020
2021
2022
2023
2024
2025

1941
1942
1943
1944
1945
1946
1947
1948
1949
1950
1951
1952
1953
1954
1955
1956
1957
1958
1959
1960
1961
1962
1963
1964
1965
1966
1967
1968
1969
1970
1971
1972
1973
1974
1975
1976
1977
1978
1979
1980
1981
1982
1983
1984
1985
1986
1987
1988
1989
1990
1991
1992
1993
1994
1995
1996
1997
1998
1999
2000
2001
2002
2003
2004
2005
2006
2007
2008
2009
2010
2011
2012
2013
2014
2015
2016
2017
2018
2019
2020
2021
2022
2023
2024
2025

The first positive identification that I have been able to make of the present standing building appears on King's Official Map Santa Fe - 1912 Portion of Block 39. The unique shape of the house is recognizable on what was then Hillside Avenue.

In 1937 when my parents bought the house it consisted of two apartments. The address then was 133 Hillside. During the housing shortage in early World War II the larger apartment was split and an attached garage converted into a bedroom. The building then took on the three apartment configuration that it has today.

The objective of this proposed project is to repair, restore, and maintain the exterior of the structure. NO changes or additions will be made except for the steel reinforcement to the porch and metal lath, both of which will be covered with stucco. The rock foundations and brick trim on the parapets will not be covered with new stucco.

Respectfully submitted,



Dorathea A. Gabel
Owner

...the ... of ...
...the ... of ...
...the ... of ...

...the ... of ...
...the ... of ...
...the ... of ...

...the ... of ...
...the ... of ...
...the ... of ...


...the ... of ...

...the ... of ...


...the ... of ...

(December 19³7






building threatened? yes	surveyed date 11/85 by HMW	county SANTA FE	ID no. 051610566
field map SFHD # 1	number 566	UTM reference easting zone 12 13	
location description		city/town SANTA FE	
501(?) P° de PERALTA 515		land grant/reservation	
building name		legal description tnsp ___ N S range ___ E W sec ___ 1/2 1/2	
film roll by SL no. SFHD# 24	negative nos. ?	loc. of neg. HPB	plan shape



date of construction	PRE 1900 estimate _____ actual _____
source	KING'S.
use	
present	residential
other	
historic	residential
other	
condition	<input type="checkbox"/> excellent <input checked="" type="checkbox"/> good <input type="checkbox"/> fair <input type="checkbox"/> deteriorating
degree of remodeling	<input checked="" type="checkbox"/> minor <input type="checkbox"/> moderate <input type="checkbox"/> major
describe:	

style	foundation material STONE
TERRITORIAL	wall material/surface BRK / STUCCO
architectural features	
STUCCO'D BRK COILING - 2 DENTIL ROWS, 1 N. HDR, 1 DOGTOOTH; COULD BE WORN OVER TOPS AS FLASHING.	
2/2 D.H. WD WINDS, SGLS, TRANS W/ S&G LINTELS, STRAIGHT PORTLAND.	
OTHER PORCH W/ SEMI-CIRC. ARCH OPENINGS.	
SGL LF 2 ARCH LIGHT WD. DOOR W/ SGL TRANS.	
3 6/6 D.H. IN BAND ON REAR E.; STAIRS TO L SIDE	
COMMENTS FRONT ENTRY: SGL IS LIGHT DOOR W/ SGL TRANS.	
WAS STUCCO'D VERY EARLY - SITING IN C. 1910 PHOTOS.	
AN EXC. BRK TERRITORIAL W/ STEPPED MASS PLAN.	

surroundings	COMM/RES
relationship to surroundings	<input type="checkbox"/> similar <input checked="" type="checkbox"/> not similar
district potential	<input type="checkbox"/> yes <input type="checkbox"/> no
significance	<input checked="" type="checkbox"/> eligible <input type="checkbox"/> of <input type="checkbox"/> none
if eligible, interest	
why? PRIMARY: STYLE, INTER.	
associated buildings?	<input type="checkbox"/> yes what type?
if inventoried, list ID nos.	
see back?	<input type="checkbox"/> yes



June 19, 1995
Box 1218
Mesilla, NM 88046

Historic Design Review Board
City of Santa Fe
200 Lincoln Ave
P.O. Box 909
Santa Fe, N.M. 87504-0909

Re: 515 Paseo de Peralta, Area #1, House #533, "Significant".

Dear Historic Board Members:

This proposal is for the repair and restoration of the exterior stucco, exterior wood surfaces, and structural integrity of the front porch on significant historic building #533, located at 515 Paseo de Peralta (Ex. A).

The building is of double brick construction covered with a rough cement stucco. The existing stucco was probably applied at the time of original construction. The bricks are roughened and pocked to hold the stucco without lath. The brick faces do not show signs of ever having been the exterior surface. I know that the existing stucco has been in place since 1937 when the building was purchased by my parents. At that time the stucco appeared to be old (See 1937 photo at Ex. B).

Due to weathering and age, the stucco has peeled and cracked in several places. There are large cracks with missing bricks in the front porch. It is proposed that those bricks be replaced and the cracks filled with a non shrinking filler. Lath would be used as necessary to hold the new stucco. The porch structure will be reinforced for safety with steel bands and plates which will be covered with stucco. This plan was recommended and endorsed by Ken DeLapp, professional and structural engineer (Ex. C).

The brick pattern in the parapets will not be covered by new stucco. The wood in the eaves, window frames, and doors will be scraped and painted. Rotten wood will be replaced as needed. The original configurations will be maintained.

The earliest record of a building on this site which I have been able to find is dated December 13, 1872 in Book Q Deeds at Page 256 and refers to "tenements and apputenances thereunto". This was on a deed filed October 1, 1887 transferring title. It is unknown to me if the "tenements and apputenances" were the existing building.

The first positive identification that I have been able to make of the present standing building appears on King's Official Map Santa Fe - 1912 Portion of Block 39. The unique shape of the house is recognizable on what was then Hillside Avenue.

In 1937 when my parents bought the house it consisted of two apartments. The address then was 133 Hillside. During the housing shortage in early World War II the larger apartment was split and an attached garage converted into a bedroom. The building then took on the three apartment configuration that it has today.

The objective of this proposed project is to repair, restore, and maintain the exterior of the structure. NO changes or additions will be made except for the steel reinforcement to the porch and metal lath, both of which will be covered with stucco. The rock foundations and brick trim on the parapets will not be covered with new stucco.

Respectfully submitted,



Dorathea A. Gabel
Owner

1. The first part of the document discusses the importance of maintaining accurate records of all transactions and activities. It emphasizes that this is essential for ensuring transparency and accountability in the organization's operations.


2. The second part of the document outlines the various methods and tools used to collect and analyze data. It highlights the need for consistent and reliable data collection processes to support informed decision-making.

3. The third part of the document focuses on the role of technology in modern data management. It discusses how advanced software solutions can streamline data collection, storage, and analysis, thereby improving efficiency and accuracy.

4. The fourth part of the document addresses the challenges associated with data management, such as data security, privacy concerns, and the integration of data from multiple sources. It provides strategies to mitigate these risks and ensure data integrity.

5. The fifth part of the document concludes by summarizing the key findings and recommendations. It stresses the importance of a proactive approach to data management to maximize the value of the organization's data assets.

December 19³7



0
1
2
3
4
5
6
7
8
9

Allen Stamm & Associates

BUILDERS REALTORS

September 18, 1953

Mrs. D. Koch Dunakin
527 Agua Fria
Santa Fe, New Mexico

Dear Mrs. Dunakin:

Enclosed is plat of the Simms property which also shows Tract I which we will receive from you, Tract G, which we will try to get the City to deed you, and Tract H which we hope to receive from the City.

5 ft. will have to remain in your ownership along the south side of Tracts H and I, as discussed previously, in order that your proposed apartment will comply with the setback restrictions of 10 ft rear yard width.

We propose to construct a wall at least 62 ft in length as shown, 8' or 9' in height with a minimum height of 8', and receive in exchange title to Tract I, less 5' along the south side as shown by the red dotted line. We will also have to build necessary retaining wall "X" approximately 14' in length at our expense. Retaining wall between Tracts A and G will be constructed by Mr. Simms to stabilize his rear yard and provide driveway from the rear of his garage to Tract G. Steps at point "Y" 5' in width will cost you \$75.00 if you want us to do the work. About \$50.00 of this is in the steps, and \$25.00 in the retaining wall which we would have to build at "X-1". If you do not wish these steps we will provide heavy crib retaining wall out of some large vigas we have, which could be removed at a later date if you build your apartments and the steps.

We will be working with our full crew there next week and will be happy to meet you at the job any time you say to discuss this matter further.


Yours sincerely,



Allen Stamm

lp
cc W. C. Simms





PROBABLE
LOCATION/ADDRESS: between
515 + 520 Paseo

H-83-042
Paseo de Peralta/Otero

