

Photographs



Front (north) and west elevations.



Front (north) and west elevations.



Front (north) of carport/storage building and west elevation of house.



HCPI 55017_157387

Front (north) elevation.



Front (north) elevation with stained-glass window.



Detail of stained-glass window, front (north) elevation.



Detail of entry stairs, north and west elevations.



Detail of entry stairs, east elevation of carport.



Detail of entryway between house (left) and carport (right).



East elevation.



East elevation.



South elevation.



South elevation portal detail.

HCPI 55017_157387



West and north (front) elevations of house and carport.



Detail of decorative corbelled brackets.



1010 Camino San Acacio: Primary Façade Diagram

Primary Façade: ———

Non-primary Façade: ———