



WALL AND PARKING AREA
STRUCTURE TO BE REPLACED
IS BEYOND



ROTTEN PERGOLA STRUCTURE TO BE REPLACED



ROTTEN PERGOLA STRUCTURE TO BE REPLACED

ROTTEN PERGOLA STRUCTURE TO BE REPLACED




ROTTEN PERGOLA STRUCTURE TO BE REPLACED



ROTTEN PERGOLA STRUCTURE TO BE REPLACED - NON-HISTORIC MATERIAL TO THE EXISTING HOUSE BUT WAS ALL RECLAIMED BARN WOOD THAT HAS STARTED TO CRACK AND BEND.





SLIDING GLASS DOOR TO BE ELIMINATED

LOCATION OF PROPOSED
NEW CLERESTORY WINDOW



LOCATION OF PROPOSED
NEW PERGOLA TO COVER
TWO SLIDING GLASS DOORS

